1(S89°47'E 2640) 2(S89°47'E 2646.60) 35 36 3(N88'54'W 2644.62) N88°54'00"W 2644.41 **T9S R27E** N88°54'00"W 1322.21 N88°54'00"W 1322.20 Sec. 36 T10S R27E W1/16 cor. 1/4 cor. Sec. 1 W1/16 S36 S1 1999 LS 2734 Scale 1"=200'

BASIS OF BEARINGS

Record Map of Survey No. 131

LEGEND

- Found 2½" iron pipe with attached 3" BLM brass cap, see Record Map of Survey No. 131.
- Set 5/8"x30" iron pin with attached 2" aluminum cap marked as shown.
- x---x Fence Line
- () Record bearing and distance.

This survey was performed at the request of Eric Nansen. The purpose of this survey was to establish the W1/16 corner as shown hereon.

After searching the available records pertaining to this survey, I found a BLM resurvey of the township line recorded as Survey No. 131 in the office of the Grant County Surveyor. I found and accepted the BLM monuments at the N1/4 corner and the NW corner of Section 1. I set the W1/16 corner on line and at the mid point between these two corners. A Land Corner Monumentation form has been recorded giving the history and details of the corner accessories for the W1/16 corner.

received and filed

AUG 6 1999

REGISTERED
PROFESSIONAL
LAND SURVEYOR le & Water OREGON
SEPT 19, 1995
JACK L. WATSON 2734

Renewal Date 6/30/2000

CORNERSTONE SURVEYING, Inc.
233 S. Canyon Blvd., John Day, Oregon 97845
(541) 575-1813

MAP OF SURVEY SITUATED IN THE SW1/4 OF SECTION 36, T9S, R27E AND IN THE NW1/4 OF SECTION 1, T10S, R27E, W.M.

GRANT COUNTY, OREGON

Date: 08/03/99

SURVEYED FOR: ERIC NANSEN

SURVEYED BY : Jack Watson

DRAWN BY: Jack Watson