


A Boundary Adjustment Survey Located
In the N1/2 of the SW1/4 of the SW1/4 of
the SW1/4 of Section 24. T. 13 S., R. 30 E.,
W.M., Grant County, Oregon.
Survey Performed in September of 1999.

T. 13 S., R. 30 E.



Basis of Bearing: The South Line of Section 24,
Grant County Map of Survey No. 1387

Ferguson Surveying
Engineering

P.O. Box 519, 210 E. Main
MT. VERNON, OR 97865
PHONE (541)932-4520
FAX (541)932-4430
EMAIL DFSE@EON1.COM

NARRATIVE

This survey was performed at the request of Burt Miller, the purpose of which is to adjust the north line of the S1/2 of the SW1/4 of the SW1/4 of the SW1/4 of Section 24, T. 13 S., R. 30 E., W.M. in order to resolve the encroachment of a building onto the adjoining property to the north and to conform to the location of a long standing fence line.

Monuments are found as shown on Map of Survey No. 1387 and the existing fence line is tied as shown. The adjusted boundary line is placed along the existing fence and monumented as shown.

The boundary agreement lines as shown on Grant County Map of Survey 374 and shown as the boundary of the Burt Miller property on Grant County Map of Survey No. 1387 were never recorded, therefore, the Section lines and subdivisional lines as shown on this survey reflect the actual boundary of record, Book 140, Page 580 of the Grant County Deed Records.



RECEIVED AND
FILED

SEPT 23, 1999
OFFICE OF COUNTY SURVEYOR
Grant County, Oregon

- Found Monument of Record, See Note at symbol.
- Set 5/8" by 30" iron pin with yellow plastic cap stamped P.L.S. 848.
- Section Line
- - - Section Subdivisional Line
- ////// Adjusted Boundary Line
- — — Boundary Agreement Line from M.O.S. 374
- XXXXXX Boundary of Record of the S1/2 of the SW1/4 of the SW1/4. See NARRATIVE.
- [Bearing/Dist.] Record Bearing and Distance as shown on Grant County Map of Survey No. 1387
- (Bearing/Dist.) Record Bearing and Distance as returned by John B. David under G.L.O. contract No. 131
- x Existing Fence

