


# BASIS OF BEARINGS



## BASIS OF BEARINGS

Map of Survey No. 1601

## LEGEND

- Found 2 1/2" aluminum pipe with attached 2 1/2" aluminum cap, see Survey No. 1601.
- Set 5/8"x30" iron pin with attached 2" alum. cap marked CORNERSTONE SURVEYING, INC. see corner restoration records for details.
- Set 3"x3" aluminum disc grouted into bedrock see corner restoration records for details.
- x—x Fence Line
- ( ) Record bearing and distance.


## NARRATIVE

This survey was performed at the request of George Meredith. The purpose of this survey was to establish the W1/16 corner and the S1/4 corner of Section 31, T12S, R31E.

A search was made of the available records pertaining to this survey and for the original corner stone at the S1/4 corner. The narrative of Survey No. 1601 gives a history of the township line and explanation of the unacceptable monuments from Survey No. 785. I set the S1/4 corner of Section 31 at single proportion on the latitudinal curve as shown on Survey No. 1601. The W1/16 corner is set at the midpoint between the SW corner of Section 31 and the S1/4 corner of Section 31.

RECEIVED AND  
FILED

SEPT. 11, 2001  
OFFICE OF COUNTY SURVEYOR  
Attest: *[Signature]*



<b>CORNERSTONE SURVEYING, Inc.</b> 233 S. Canyon Blvd., John Day, Oregon 97845 (541) 575-1813	
<b>MAP OF SURVEY</b> <b>SITUATED IN THE SW1/4 OF SECTION 31</b> <b>T12S, R31E, W.M.</b>	
GRANT COUNTY, OREGON	
SURVEYED FOR: <b>GEORGE MEREDITH</b>	
SURVEYED BY : Jack Watson	Date: 9/06/2001
DRAWN BY : Jack Watson	

MAP OF SURVEY NO. 1610