

## BASIS OF BEARINGS

Station "Kimberly" to "Kimberly Az Mark"  
S43°07'42"E

## LEGEND

- Set 5/8"x30" iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC. Unless otherwise shown.
- X—X Fence Line

## NARRATIVE


This survey was performed at the request of John Thomas. The purpose of this survey was to monument the proposed boundary adjustment lines as shown hereon.

The north boundary of Parcel 2, Land Partition No. 2001-05 was adjusted and monumented. The adjusted boundary was monumented at the location approved by Mr. Thomas.

RECEIVED AND  
FILED

DEC. 28, 2001

Robert D. Anglin  
Surveyor



<b>CORNERSTONE SURVEYING, Inc.</b> 233 S. Canyon Blvd., John Day, Oregon 97845 (541) 575-1813	
<b>MAP OF SURVEY</b> Proposed Boundary Line Adjustment Situated in the NW1/4 Section 29 T9S, R26E, W.M. GRANT COUNTY, OREGON	
SURVEYED FOR: <b>THOMAS ORCHARDS, Inc.</b>	
SURVEYED BY : Jack Watson	Date: 12/20/2001
DRAWN BY : Jack Watson	

MAP OF SURVEY NO. 1621