

Scale 1"=100'

BASIS OF BEARINGS

SURVEY NO. 717


LEGEND

- Found 5/8" iron pin with attached yellow plastic cap, see Survey No. 717 unless otherwise shown.
- Set 5/8"x30" iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC.
-) Record bearing and distance.
- Found monument, see record map of survey number shown in box.

NARRATIVE

This survey was performed at the request of Penny Bennett. The purpose of this survey was to establish the proposed boundary adjustment as shown. The entire property is described in Instrument No. 203032, deeds of Grant County, Oregon.

A search was made of the available records pertaining to this survey and field measurements were made to locate the monuments shown. The new monuments were set in accordance with the evidence found. The county road right of way alignment shown on Survey No. 717 was used. The proposed boundary line was extended to intersect this right of way.



Renewal Date 6/30/2004

CORNERSTONE SURVEYING, Inc.

233 S. Canyon Blvd., John Day, Oregon 97845 (541) 575—1813

MAP OF SURVEY
PROPOSED PROPERTY LINE ADJUSTMENT
SITUATED IN THE SE1/4 OF SECTION 32
AND IN THE SW1/4 OF SECTION 33, T13S, R30E, W.M.

GRANT COUNTY, OREGON

SURVEYED FOR: PENNY BENNETT

SURVEYED BY : Jack Watson

DRAWN BY: Jack Watson

Date: 01/20/2004