(N 89°45'W 79.66ch.)

N 89° 33′ 23″ W 5296.95 (N 89°45′W 39.83ch.) (N 89°45'W 39.83ch.) 17 | 16 1/4 cor. N 89°33'23"W 2648.48 N 89° 33′ 23″ W 2648.47 1324.24 1324.23 At section cor. found 2"galvanized iron pipe with brass cap set by U.S. Forest Service. 21 22 At section cor. found 2" aluminum pipe with aluminum cap set by U.S. Forest A diligent search was made for the 1/4 cor.
No evidence of its position was found. At single proportionate measure, I set a 11/2" x 30" iron pipe with Grant County Surveyor Brass Cap attached. SEE ENLARGED DETAIL AT RIGHT NWI/4 NEI/4 21 22 20 21 28 27 29 | 28

SCĂLE I" = 500'

BASIS OF BEARINGS SOLAR OBSERVATION

E 1/16 cor. SEC. 15 1/4 cor. N 89° 33′ 23″ W 1324.24 SEC. 21 ENLARGED DETAIL SCALE I" = 200'

## LEGEND

SET 5/8"x 30" IRON PIN RECORD BEARING AND DISTANCE x---x FENCE

REFERENCES

G.L.O. FIELD NOTES RECORDED REMONUMENTATION SHEETS

OREGON JULY 12, 1963 ROBERT D. BAGETT 598

REGISTERED PROFESSIONAL

LAND SURVEYOR

NARRATIVE: This survey was performed at the request of Brice Lemons to locate the north line of the NWI/4 NEI/4 of Section 21, T.I5S., R.30E., W.M.

A search was made of the available records pertaining to this survey. Field measurements were made to locate existing monuments. New monuments were set in accordance with evidence found.

NOTE: See recorded remonumentation sheets for information concerning remonumented corners.

**BAGETT, GRIFFITH & ASSOCIATES** John Day, Oregon

Map of Survey

NORTH LINE NWI/4 NEI/4 SECTION 21, T. 15 S., R. 30 E., W.M.

GRANT COUNTY, OREGON

BRICE LEMONS SURVEYED FOR 5/5-5/6/80 R.D.B. & G.L.E. SURVEYED BY Drawn by: G.L.E. 5/7/80 Scale: AS SHOWN

RECEIVED AND

OFFICE OF (1) 1111 Y SURVEYOR

Attest Of Authority of Colerand