

I do hereby certify that this plat was received on the 13 day of 1998 at 120 clock 2 M., and recorded as Land Partition Plat No. 28-4

Kathy McKinger Grant Gounty Clerk By Mary Marelton, Deputy

Bill E. Wilson and Theresa L. Wilson, husband and wife, have consented to the declaration of this Partition by an Affidavit of Consent recorded as Instrument No. 961934,

I do hereby certify that this is a true and exact copy of Land Partition No. 28-04

KATHY McKINDEN
Grant Clerk By Mary Moulton, Deputy

I do hereby certify that this is a true and exact copy of Land Partition No. 98-64

Beginning at the SW corner of Parcel 3, Land Partition Plat No. 96–18, which I designate to be the Initial Point of this Land Partition, being 2.26 feet north and 1115.58 feet east of the W1/4 corner of Section 27; thence N00°54′09″E, 1783.16 feet to the southerly right of way line of County Road No. 74–B; thence N80°37′00″E, along said right of way line, 135.28 feet; thence continuing along said right of way line, 122.05 feet along the arc of a 160.22 foot radius curve left, the long chord of which bears (N58°47'35″E, 119.12 feet); thence S00°45'44″W, 1866.40 feet to the south line of the NW1/4 of Section 27; thence S89°53'02″W, along the south line of the NW1/4 of Section 27, 238.61 feet to the point of beginning.

Said tract containing 9.81 acres.

Cornerstone Surveying, Inc. 233 S. Canvon Blvd. John Day, OR. 97845

(541)575-1813

REGISTERED **PROFESSIONAL** LAND SURVEYOR

Me Silato OREGON SEPT 19, 1995 JACK L. WATSON 2734

Renewal Date 6/30/98

## **NARRATIVE**

This survey was performed at the request of Chuck Church. The purpose of this survey was to partition Parcel 3 of Land Partition Plat No. 96—18 into 3 parcels, as shown hereon.

After searching the available records pertaining to this survey, I found that the corners of this property were established during Record Survey No.'s 324, 576 and Land Partition No. 96-18. I found the monuments of parcel 3 as shown on Land Partition No. 96-18 in good condition and I accepted them for the boundary of this partition. The division lines between Parcels 1, 2 and 3 were established at locations approved by Mr. Church.

This survey was performed with a Topcon GTS-4 total station, with a closed loop random

No.47).

(3) A private easement, including the terms and provisions thereof, recorded August 8, 1978, in Book 119, Page 525, deed records for Grant County, Oregon. An easement in common with others for ingress and egress to abutting subject property to the east.

(4) Reservation, including the terms and provisions thereof, in deed from R.L.C. Investments, Inc. a corporation, dated June 18, 1979, recorded August 15, 1979, in Deed Book 121, Page 512, deed records for Grant County, Oregon, to wit: "RESERVING unto Grantor, its successors and assigns, an easement in common, over and along that portion of Easement "B" that traverses the property first described above, for the purpose of ingress and egress to County Road No. 47.".

(5) An easement, including the terms and provisions thereof, to C. P. National Corporation, a corporation, recorded February 21, 1980, in Book 122, Page 515, deed records of Grant County, Oregon. Right of way easement for utility and incidental purposes, 30 feet in width, as shown hereon.

(6) Right of Way Deed and Release of easement, including the terms and provisions thereof, between Wiley W. Files, III, Grantor, and Grant County, Oregon, a municipal corporation,
Grantee, dated March 24, 1992, recorded April 1, 1992, in the records of Grant County, Oregon,

(7) A private 50' wide access easement, including the terms and provisions thereof, dated December 19, 1997, recorded December 19, 1997, in Deeds Instrument No. 972508, deeds of


Charles T. Echurch

RECEIVED AND FILED **JAN 1 6 1998** 


**ACKNOWLEDGEMENT** 

STATE OF OREGON SS

This instrument was acknowledged before me on this 13 day of January, 1998, by Charles T. Church.







## LEGEND

- Found 5%" iron pin with attached yellow plastic cap marked BGA SURVEY MARKER. Unless otherwise shown.
- Found \( \frac{5}{8}'' \) iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC. see Land Partition Plat No. 96-18.
- O Set \( \frac{5}{8}'' \times 30'' \) iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC.

X —— X Fence line.

- ) Map of Survey No. 324 record bearing
- )) Land Partition Plat No. 96-18 record bearing
  - Found monument, see record survey number

NOTE: I find no record or existance of a Geodetic Control monument within 1/2 mile of this Land