


CORNER RESTORATION

CORNER: SW 1/16 Sec:11 TWP: 10S. RANGE:26E.

ORIGINAL SURVEY BY:
CONTRACT NUMBER: (Corner not previously established.)
CONTRACT DATE:



ORIGINAL DESCRIPTION: Corner not previously established.

RESTORATION BY, STAMP AND DATE:

R.D. Bagett
G.J. Russell
R.J. Lewis

RECEIVED AND
FILED

JUL 27 1994

OFFICE OF COUNTY SURVEYOR
Robert D. Bagett
Attest: *Jeremy Russell*

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1993
ROBERT D. BAGETT
598

Renewal Date 12/31/94

May 9, 1994

EVIDENCE FOUND: None.

See Record Map of Survey No. 1320.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

At the corner point: I set a 5/8"x30" iron pin, 30" in the ground, with attached aluminum cap marked as shown.

From which I SCRIBE NEW BEARING TREES:
A Douglas Fir 10"diam., bears S.12°E., 41.1 ft., marked 1/16 S11 BT.
A Juniper 8"diam., bears S.50°W., 65.8 ft., marked 1/16 S11 BT.

MONUMENT MARKED

BGA
SURVEY MARKER
SW 1/16

S11
1994
OPLS 598

Raised a mound of stone 2 ft. base around cap. Used mag. compass with 20°E var. and a steel tape, measuring to a 50d nail driven in the sidecenter at the root crown of the BT's. Attached BT tags to BT's.