

CORNER RESTORATION


CORNER: CE 1/16 Sec:13 TWP: 10S. RANGE:26E.

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:

(Corner not
previously
established.)



ORIGINAL DESCRIPTION: Corner not previously established.



RESTORATION BY, STAMP AND DATE:

R.D. Bagett
G.J. Russell
R.J. Lewis

RECEIVED AND
FILED

JUL 27 1994

OFFICE OF COUNTY SURVEYOR
Attest: *Robert D. Bagett*
Gary Russell



Renewal Date 12/31/94

May 11, 1994

EVIDENCE FOUND: None.

See Record Map of Survey No. 1320.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: I set a 5/8"x30" iron pin, 30" in the ground, with attached aluminum cap marked as shown.

From which I SET NEW BEARING OBJECTS:

A 2½" cross chiseled in the face of a 15' high rim approximately 2' above the base, bears N.67°E., 15.9 ft., marked X BO.

MONUMENT MARKED

BGA
SURVEY MARKER
E 1/16
C—C
S13
1994
OPLS 598

Raised a mound of stone 2 ft. base around cap. Used mag. compass with 20°E var. and a steel tape, measuring to a 50d nail driven in the sidecenter at the root crown of the BT's. Attached BT tags to BT's.