


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. M-22

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.



Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 15" in the ground and raised a mound of stone & earth around the pipe.


From Which:

A Juniper 6" dia., Bears S78°W., 26.2 ft., scribed: SW 1/16 S13 BT

A Pine 8" dia., Bears N88°E., 14.0 ft., scribed: SW 1/16 S13 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, 5 ft. West & South from the corner.



This work is performed by:  
Douglas M. Ferguson PLS 848  
Mt. Vernon Oregon.  
On: Sept. 10, 1985  
Refer to Map of Survey No. 920

Office of Surveyor County of Grant  
State of Oregon hereby certify that the within instrument was filed in this office  
for record on the 27th day of June, 1986  
Robert M. Bayne by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)