


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by W.H. Byars under General
Land Office Contract No. 197 dated July 14, 1873.

Surveyor General's records state:

Set a volcanic stone 20x8x4 for the quarter section
corner.



Description of corner evidence found:

At the assumed corner location found a basalt stone 21"x8"x4" set 11"
in ground marked "1/4" on North face in East side of stone mound
2 1/2 feet in diameter.

Description of monument and accessories established to perpetuate the
original location of this corner:

As evidence found agrees with the G.L.O. original record,
at the location of the found original marked stone in
mound set a 30" long 2 1/2" O.D. aluminum pipe 12" in
ground to bedrock with a 3 1/4" aluminum cap marked:

Marked new bearing tree:

A Juniper, 8" DBH, bears South 37° West, 126.8 feet
distance, scribed "1/4 S4 BT".

Raised stone mound 2 1/2 feet diameter at base to top of
cap, and buried original stone North of cap.



Painted 6" red band and painted face red and nailed a
brass washer stamped "LS 1026" and nailed signs 54-3
and 54-4 on bearing tree.

Set steel post with sign 54-4 bolted to post beside cap.

I hereby certify the above described corner monument was re-established
as herein described on July 29, 1981.

Witnesses: William S. DeGroot
William S. DeGroot, LS 1633

Shelby H. Griggs
Shelby H. Griggs, Chainman



Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 19 day of Oct, 1981.
Robert H. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)