


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by W.H. Byars under General
Land Office Contract No. 197 dated July 14, 1873.

Surveyor General's records state:

Set a basaltic stone 14x12x4 for quarter sec. corner.



Description of corner evidence found:

No evidence found, considered lost and re-established by
proportion. The corner location falls in a tractor logging
skid trail and cleared ^{area} on north slope of ridge. An
intensive search failed to recover any evidence of
original corner location.

Description of monument and accessories | established to perpetuate the
original location of this corner:


At proportionate location, set 30" long 2 1/2" O.D. aluminum pipe
18" in ground to bedrock with 3 1/4" aluminum cap marked:

Marked new bearing trees:

A Douglas Fir, 9" DBH, bears South 24° East, 59.2 feet,
scribed "1/4 S7 BT";

A Douglas Fir, 11" DBH, bears North 88° West, 54.2 feet,
scribed "1/4 S12 BT";

Raised stone mound 2 feet base to cap. Painted 6" red
band and faces red and nailed brass washer stamped
"LS 1026" and signs 54-3 and 54-4 on bearing trees.
Set steel post with sign 54-4 north of cap.



I hereby certify the above corner monument was re-established
as herein described on August 12, 1981.

Witnesses:

William S. DeGroot
William S. DeGroot, LS 1633
Shelly H. Griggs
Shelly H. Griggs, Chainman

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 1st day of Oct, 1981.
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)

