

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. J-15

History of original corner establishment:

Corner was originally established in Sept., 1881,
By Bamford Robb, U.S. Deputy Surveyor, under
Contract No. 383. Surveyor Generals Notes State:
Set basalt stone 15x7x6 for 1/4 sec. cor.
from which.
A Pine 7 in. dia. bears N12°E., 16 lks. dist.
" " 8 " " " S70°W., 40 " "

DIAGRAM

T10S R29E
S10
1/4-.-
S15
1984
PLS 848

Description of corner evidence found:

No evidence of original stone is found, all traces
have been destroyed by fencing and logging activity.

The original Bearing trees have been lost to logging.
Therefore established corner position by single proportion
measure between corners found 1/2 mi. East & West.

Description of monument and accessories | established to perpetuate the
original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 24" in the ground.
From Which.
A Fir 12" dia. Bears, S 70°W., 68.0 ft. scribed: 1/4 S15 BT
A Fir 12" dia. Bears, N53°E., 61.4 ft. scribed: 1/4 S10 BT
Measurements to trees taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing
Tree Sign above blaze, and warning sign on back of each tree. Painted
a 6" red band at breast ht. around each tree. Set steel fence post with
warning Sign, South 3 ft. from the corner.

Refer to map of survey No. 874



Work by D.M. Ferguson, PLS 848, Mt. Vernon Ore.
On Oct. 20, 1984
Witnessed by J. David Brinton, PLS 2065

Office of Survey County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 27 day of July, 1985
Robert D. Brinton by _____
(COUNTY OFFICIAL) (DEPUTY)