


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by W.A. Byars under General Land Office Contract No. 197 dated July 14, 1873.

Surveyor General's Records state:

Set a volcanic stone 12x10x8 for quarter section corner.



Description of corner evidence found:


No evidence found, considered lost and re-established by proportion. An intensive search revealed no evidence of a marked stone or stone mound. Corner falls in edge of timber on east slope of ridge with some logging in area.

Description of monument and accessories established to perpetuate the original location of this corner:

At proportionate location, set 30" long 2 1/2" O.D. aluminum pipe 26" in ground with 3 1/4" aluminum cap marked:

Marked new bearing trees:

A Ponderosa Pine, 15" DBH, bears North 30° East, 6.2 feet, scribed "1/4 S18 BT";
A Juniper, 6" DBH, bears South 87 1/2° West, 15.0 feet, scribed "1/4 S13 BT".
Raised stone mound 2 feet base to cap. Painted 6" red band and faces red and nailed brass washer stamped "LS 1026" and signs 54-3 and 54-4 on bearing trees. Set steel post with sign 54-4 south of cap.



I hereby certify the above corner monument was re-established as herein described on August 12, 1981.

Witnesses: William S. DeGroot
William S. DeGroot, LS 1633

Shelby H. Griggs
Shelby H. Griggs, Chainman

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 15 day of Oct, 1981
Robert H. Leggett by _____
(COUNTY OFFICIAL) (DEPUTY)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David B. Armstrong
9/21/81 OREGON
AUGUST 22, 1975
DAVID B. ARMSTRONG
1026