


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Bamford Robb under joint
General Land Office Contract No. 383 dated
March 26, 1881.

Surveyor General's records state:

Set a basalt stone 17x9x8 in mound of stones for
1/4 sec. cor.



Description of corner evidence found:

The assumed corner position fell in an extremely rocky area.
No remaining evidence of the original corner stone or any stone
mounds were found in the vicinity. A Form 458 was found nailed
to a Juniper tree approximately 100 feet SE of assumed corner area.

Description of monument and accessories established to perpetuate the
original location of this corner:

At the single proportioned point set a 30" long 2 1/2"
O.D. aluminum pipe 2" in ground to bedrock with 3 1/4"
aluminum cap marked as shown:

Marked new bearing trees:



A Juniper, 10"DBH, bears South 34° East. 96.9 feet,
scribed "1/4 S16 BT";
a Juniper. 5"DBH, bears North 70° West, 55.1 feet,
scribed "1/4 S17 BT".

Raised stone mound 3 feet base to cap.
Painted 6" red band and faces red and nailed brass washers
stamped "LS 1026" and signs 54-3 and 54-4 on bearing
trees. Set steel posts with signs 54-2 and 54-4 north
and south of cap.

I hereby certify the above corner was re-established as
herein described on August 3, 1981.

Witnesses: William S. DeGroot
William S. DeGroot, LS 1633

Shelby H. Griggs
Shelby H. Griggs, chainman



David B. Armstrong
9/25/81 OREGON
AUGUST 22, 1973
DAVID B. ARMSTRONG
1026

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 19 day of Oct, 1981
Robert H. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)