

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. N-15

History of original corner establishment:

Corner was originally established in Sept., 1881,
By Bamford Robb, U.S. Deputy Surveyor, under
Contract No. 383. Surveyor General's Notes State:
Set basalt stone 18x10x6 in mound of stone, for
1/4 sec. cor.

DIAGRAM

T108 R29E
S15
1/4-.-
S22
1984
PLS 848

Description of corner evidence found:

No trace of original stone or stone mound is found,
Corner fall in a draw bottom which has scoured and
washed out all evidence.

No bearing trees where originally established.

Therefore determined corner position by single
proportionate measurement from corners found 1/2 mi.
East & West.

Description of monument and accessories | established to perpetuate the
original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 27" in the ground.

From Which.

A Juniper 13" dia. Bears, S86°W., 18.9 ft., scribed: 1/4 S22 BT.

A Juniper 12" dia. Bears, N13°W., 32.5 ft., scribed: 1/4 S15 BT

Measurements to trees taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing
Tree Sign above blaze, and warning sign on back of each tree. Painted
a 6" red band at breast ht. around each tree. Set steel fence post with
warning Sign, North 2.5 ft. from the corner.

Refer to map of survey No. 874

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Work by D.M. Ferguson, PLS 848, Mt. Vernon Ore.
On Oct. 19, 1984

Witnessed by J. David Brinton, PLS 2065

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 22 day of July, 1985
Robert L. Dager by _____
(COUNTY OFFICIAL) (DEPUTY)