

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. 0-12

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T10S R29E
NE 1/16
S21
1986
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 6" in the ground and raised a mound of stone and earth around the pipe.

From Which:

A forked Juniper in the fence Bears S62°E., 16.1 ft., scribed NE 1/16 S21 BT
A Juniper 8" dia., Bears N40°E., 32.1 ft., scribed: NE 1/16 S21 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North and West 1.5 ft. from the pipe, in the stone mound as constructed around the pipe.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1888
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: March 24, 1986
Refer to Map of Survey No. 927

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 20 day of June, 1986
Robert D. Bayless by _____
(COUNTY OFFICIAL) (DEPUTY)