

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-19

History of original corner establishment:

Corner not previously established.

**DIAGRAM**  
T108 R29E  
C1/4  
S23  
1984  
PLS 848

Description of corner evidence found:

Corner not previously established.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 25" in the ground.

From Which.

A Fir, 20" dia. Bears, N70° 06'E., 22.2 ft., scribed: C1/4 S23 BT

A Fir, 10" dia. Bears, S 6° 35'W., 23.6 ft., scribed: C1/4 S23 BT

Measurements to trees with total station electronic equipment, angles are measured from the control traverse.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, alongside corner.

Refer to map of survey No. 875



Work by D.M. Ferguson, PLS 848, Mt. Vernon Ore.  
On Oct. 25, 1984

Witnessed by J. David Brinton, PLS 2065

Office of.....*Surveyor*.....<sup>12</sup> County of.....*Grant*.....  
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office  
for record on the *27* day of *July*, 19*85*.  
*David H. Brinton* by .....  
(COUNTY OFFICIAL) (DEPUTY)