

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. R-6
History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T10S R29E
S20
W1/16-.-
S29
1986
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 14" in the ground and raised a 3'x 10" mound of stone and earth around the pipe.

From Which:

A Pine 8" dia., Bears N25°W., 22.5 ft., scribed: W1/16 S20 BT

A Juniper 14" dia., Bears S46°E., 54.2 ft., scribed: W1/16 S29 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with Boundary Sign, approx. 80 ft. North and nailed Warning & Boundary signs to a 3" Juniper, 21.9 ft. East. (Posts will not drive & no rocks to mound)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: March 27, 1986
Refer to Map of Survey No. 927

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the *22* day of *June*, 19*86*
.....*Robert D. Sayett*..... by
(COUNTY OFFICIAL) (DEPUTY)