

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. R-14

History of original corner establishment:

Corner not previously established

DIAGRAM 29E
S22
W1/16--
S27
1984
PLS 848


Description of corner evidence found:

Corner not previously established.

Description of monument and accessories | established to perpetuate the
original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 20" in the ground, and raised a mound of stone around
the pipe,
From Which:
Set 5/8"x30" iron pins with plastic caps stamped PLS 848, and guard posts
with warning, boundary & Bearing tree signs alongside pins, as follows:
North 10.7 ft. and East 7.1 ft. from the corner.
Measurements taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.

Refer to map of survey No. 874



Work by D.M. Ferguson, PLS 848, Mt. Vernon Ore.
On Oct. 10, 1984
Witnessed by J. David Brinton, PLS 2065

Office of..... *Surveyor* County of..... *Grant*
State of..... *Oregon* I hereby certify that the within instrument was filed in this office
for record on the..... *27th* day of..... *July*..... 19..... *85*.....
Robert H. Brinton by
(COUNTY OFFICIAL) (DEPUTY)