

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. R-15

History of original corner establishment:

Corner was originally established in July, 1873,
By W.M. Byars, U.S. Deputy Surveyor, under
Contract No. 197. Surveyor Generals Notes State:
Set a Basalt Stone 18x10x4, for the Quarter
Section Corner.

DIAGRAM

T10S R29E
S22
1/4-.-
S21
1984
PLS 848

Description of corner evidence found:

Found a 18"x10"x8" stone, set in the ground, with
1/4 on North face. Set 3 ft. south from North & West
fence corner.


No accessories originally established.
Accepted position of the stone as the 1/4 corner.

**Description of monument and accessories established to perpetuate the
original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 14" in the ground, placed orig. stone, south alongside
pipe, and raised a mound of stone around the pipe.
From Which.

Set 5/8"x30" iron pins with plastic cap stamped PLS 848, and guard posts with
warning, boundary and bearing tree sings, as follows.
N 5° E., 5.2 ft. & West, 5.1 ft. from the Corner. (No Trees available)
Measurements taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.

Refer to map of survey No. 874



Work by D.M. Ferguson, PLS 848, Mt. Vernon Ore.
On Oct. 10, 1984
Witnessed by J. David Brinton, PLS 2065

Office of Surveyor County of Grant
State of Oregon hereby certify that the within instrument was filed in this office
for record on the 22 day of July, 1985
Robert D. Brinton by _____
(COUNTY OFFICIAL) (DEPUTY)