


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original section corner established by
W.H. Byars under Contract Number 197, dated July 4, 1873.

The original General Land Office notes state:

40.00 Set basalt stone 18"x10"x6" for the $\frac{1}{4}$ Section
Corner.




Description of corner evidence found:

A stone 18"x10"x6" marked $\frac{1}{4}$ on South Face.

No bearing trees found.
None of record.

Description of monument and accessories | established to perpetuate the
original location of this corner:

I replaced the original corner stone with a 2 $\frac{1}{2}$ "x30" iron pipe
with brass cap set 26" in the ground 4" above for the $\frac{1}{4}$ section
corner 4-5 T10S R30E. Bury original stone alongside.



The following bearing objects were set:

36" #5 rebar with yellow plastic cap
under fence. N. 90° W., 30.0 ft. 4"
above ground.

36" #5 rebar with yellow plastic cap
under fence. S. 0° E., 30.0 ft. 8"
above ground.

36" #5 rebar with yellow plastic cap
under fence. N. 22° E., 30.0 ft. 4"
above ground.

Above plastic caps are marked B0



Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 23 day of Aug, 1979
Robert H. Beggs by _____
(COUNTY OFFICIAL) (DEPUTY)

RECEIVED AND
FILED