

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. 0-2

History of original corner establishment:  
Grant County Survey Records show  
no previous establishment of this  
corner.

**DIAGRAM**

T10S R30E  
NW 1/16  
S19  
1984  
PLS 848

**Description of corner evidence found:**

Grant County Survey Records show no  
previous establishment of this Cor.

**Description of monument and accessories I established to perpetuate the  
original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown  
on the **DIAGRAM**, SET 27" in the ground.

From Which.

A Tamarack 14" dia. Bears, N 6°W., 23.4 ft., scribed: NW 1/16 S19 BT

A Fir 12" dia. Bears, S84°E., 18.8 ft., scribed: NW 1/16 S19 BT

Measurements to trees taken with a metal tape and magnetic compass,  
with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing  
Tree Sign above blaze, and warning sign on back of each tree. Painted  
a 6" red band at breast ht. around each tree. Set steel fence posts with  
warning & Boundary Signs, East & West 4 ft. from the corner.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 12, 1968  
DOUGLAS M. FERGUSON  
848

This work is performed by:  
Douglas M. Ferguson PLS 848  
Mt. Vernon Oregon.  
On: Nov. 6, 1984  
Refer to Map of Survey No. 908

Office of Surveyor County of Grant  
State of Oregon I hereby certify that the within instrument was filed in this office  
for record on the 13 day of Mar, 1986  
Robert D. Bays (COUNTY OFFICIAL) by (DEPUTY)