

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally set in a survey, dated 7/4/80, by Clell Goodwin, PLS 1078, for the USFS under cadastral contract No. 53-04H1-9-7631N.

DIAGRAM

T10S R30E
N 1/16
S20 S21

Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the

original location of this corner: At the corner location as determined by the aforementioned survey, I set a 2½" x 30" aluminum pipe with a 3½" cap and a magnet in the base marked as shown:

New Sec. 20 BT:

Marked 10" fir with upper and lower axe face. Bears S 81°30'W 58.9 ft. scribed "N 1/16S 20 BT". Tagged with brass washer marked "PLS 1078".

New Sec. 21 BT:

Marked 10" fir with upper and lower axe face. Bears N 89° E 50.7 ft.

Scribed "N 1/16 S21 BT". Tagged with brass washer marked "PLS 1078".

Fence Corner (fences East, West and South). Bears S 59° W 47.1 Ft.

T10S R30E
N 1/16
S 20 S 21
1980
PLS 1078

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Clell Goodwin

OREGON
JULY 30, 1976
CLELL GOODWIN
1078

I hereby certify the above corner monument was re-establishing as herein described on June 12, 1980.

CLELL GOODWIN, P.L.S.

Witness: /s/ Jeff Clark

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 31 day of Oct, 1980
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)