

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-3

History of original corner establishment:

Grant County Survey Records show no previous establishment of this corner.

DIAGRAM

T10S R30E
C1/4
S19
1984
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 16" in the ground, and raised a mound of stone & earth around the pipe.

From Which:

A Pine 14" dia., Bears, N 2⁰E., 45.3 ft., scribed: C1/4 S19 BT

A Juniper 6" dia., Bears, S25⁰E., 12.1 ft., scribed: C1/4 S19 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, South 5 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1966
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Oct. 18, 1984
Refer to Map of Survey No. 908

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office
for record on the.....*17*..... day of.....*March*....., 19.....*86*.....
.....*Robert D. Bryant*..... by.....
(COUNTY OFFICIAL) (DEPUTY)