

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-10

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM


T10S R30E
W1/16
C--C
S21
1985
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 28" in the ground.
From Which.
A Fir 6" dia., Bears N37°W., 8.5 ft., scribed: C-W 1/16 S21 BT
A Fir 8" dia., Bears S27°W., 26.9 ft., scribed: C-W 1/16 S21 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 4" red band at breast ht. around each tree. Set steel fence post with warning & Boundary Signs, East 4 ft. from the Corner.



This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: May 10, 1985
Refer to Map of Survey No. 913

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*12* day of.....*May*....., 19.....*85*.....
.....*Robert D. Baggett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)