

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-12

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T10S R30E
E1/16
C-.-C
S21
1985
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 25" in the ground.


From Which.

A Fir 10" dia., Bears N11°E., 12.4 ft., scribed: C-E 1/16 S21 BT

A Fir 7" dia., Bears S12°W., 24.5 ft., scribed: C-E 1/16 S21 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, South & West 4 ft. from the corner.



This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: May 10, 1985
Refer to Map of Survey No. 913

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 12 day of May, 1986
Robert D. Light by _____
(COUNTY OFFICIAL) (DEPUTY)