

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally set in a survey, dated 7/4/80, by Clell Goodwin, PLS 1078, for the USFS under cadastral contract No. 53-04H1-9-7631N.

DIAGRAM

T10S R30E

SW 1/16

S 20

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the

original location of this corner: At the corner location as determined by the aforementioned survey, I set a 2½" x 30" aluminum pipe with a 3½" cap and a magnet in the base marked as shown:

New BT:

Marked 13" fir with upper and lower axe faces. Bears S 5° E 32.7 ft. Scribed "SW 1/16 S 20 BT". Tagged with brass washer marked "PLS 1078".

New BT:

Marked 18" fir with upper and lower axe faces. Bears N 84° W 32.2 ft. Scribed "SW 1/16 S 20 BT". Tagged with brass washer marked "PLS 1078".

T10S R30E
SW 1/16S20
1980
PLS 1078REGISTERED
PROFESSIONAL
LAND SURVEYOR

Clell Goodwin

OREGON
JULY 30, 1976
CLELL GOODWIN
1078

I hereby certify the above corner monument was re-established as herein described on June 3, 1980.

CLELL GOODWIN, P.L.S.

Witness: /s/ Jeff Clark

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 31 day of Oct, 1980
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)