

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

Corner originally set in a survey, dated 7/4/80, by Clell Goodwin, PLS 1078, for the USFS under cadastral contract No. 53-04H1-9-7631N.

**DIAGRAM**

T10S R30E

(SE) 1/16

S 20

## Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner: At the corner location as determined by the aforementioned survey, I set a 2½" x 30" aluminum pipe with a 3½" cap and a magnet in the base marked as shown:

## New BT:

Marked 8" fir with upper and lower axe faces.  
Bears S 44°30'W 58.7 ft. Scribed "SE 1/16 S20 BT".  
Tagged with brass washer marked "PLS 1078".

T10S R30E  
SE 1/16

## New BT:

Marked 20" fir with upper and lower axe faces.  
Bears S 44° E 8.7 ft. Scribed "SE 1/16 S20 BT".  
Tagged with brass washer marked "PLS 1078".

S 20  
1980  
PLS 1078

I hereby certify the above corner monument was re-established as herein described on June 3, 1980.

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Clell Goodwin*

OREGON  
JULY 30, 1976  
CLELL GOODWIN  
1078

\_\_\_\_\_  
CLELL GOODWIN, P.L.S.

Witness: /s/ Jeff Clark

Office of Surveyor County of Grant  
State of Oregon I hereby certify that the within instrument was filed in this office  
for record on the 31 day of Oct, 1980  
Robert D. Bayne by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)