


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally set in a survey dated 7/4/80, by Clell Goodwin PLS 1078 for the USFS under cadastral contract No. 53-04H1-9-7631N.



Description of corner evidence found:

None



Description of monument and accessories I established to perpetuate the original location of this corner: At the corner location as determined by the aforementioned survey, I set a 2½" x 30" aluminum pipe with a 3½" cap and a magnet in the base marked as shown:

New Sec. 20 BT:


Marked 10" juniper with upper and lower axe faces.
Bears N 31°30' E 28.8 ft. Scribed "W 1/16 S 20 BT".
Tagged with brass washer marked "PLS 1078".

New Sec. 29 BT:

Marked 8" juniper with upper and lower axe faces.
Bears S 30°30' E 35.8 ft. Scribed "W 1/16 S 29 BT".
Tagged with brass washer marked "PLS 1078".



Clell Goodwin



I hereby certify the above corner monument was re-established as herein described on June 3, 1980.

CLELL GOODWIN, P.L.S.

Witness: /s/ Jeff Clark

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 31 day of Oct, 1980
Robert D. Bayard by _____
(COUNTY OFFICIAL) (DEPUTY)