

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. S-23

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T10S R30E
C
N1/16 S25
C
1985
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 25" in the ground.
From Which.
A Fir 18" dia., Bears N74°E., 20.3 ft., scribed: C-N 1/16 S25 BT
A Pine 14" dia., Bears S11°W., 8.6 ft., scribed: C-N 1/16 S25 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, East 4 ft. & West 3 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1988
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Aug. 21, 1985
Refer to Map of Survey No. 919

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 12 day of June, 1986
Robert D. Dugan (COUNTY OFFICIAL) [Signature] (DEPUTY)