

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. T-7

History of original corner establishment:

Grant County Survey Records show no previous establishment of this corner.

DIAGRAM

T10S R30E
C1/4
S29
1984
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 10" in the ground, & raised a mound of stone and earth around the pipe.

From Which:

A Juniper 10" dia. Bears, N25°E., 6.4 ft., scribed: C1/4 S29 BT

A Pine 8" dia. Bears, S76°E., 56.1 ft., scribed: C1/4 S29 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North 5 ft. & West 1 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1988
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Nov. 7, 1985
Refer to Map of Survey No. 908

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 12 day of Mar, 1986
Robert D. Buzza by _____
(COUNTY OFFICIAL) (DEPUTY)