

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. T-8

History of original corner establishment:

Grant County Survey Records show no previous establishment of this corner.

DIAGRAM

T10S R30E
E 1/16
C--C
S29
1984
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 18" in the ground, and raised a mound of stone & earth around the pipe.

From Which:

A Juniper 6" dia. Bears, N14°E., 7.0 ft., scribed: C-E 1/16 S29 BT

A Juniper 6" dia. Bears, S18°W., 15.6 ft., scribed: C-E 1/16 S29 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, South & East 4 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Nov. 8, 1985
Refer to Map of Survey No. 908

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*12*..... day of.....*Mar*....., 19..*86*..
Robert D. Leggett by.....
(COUNTY OFFICIAL) (DEPUTY)