

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. T-11

History of original corner establishment:
Grant County Survey Records show no
previous establishment of this Cor.

DIAGRAM

T10S R30E
C1/4
S28
1985
PLS 848

Description of corner evidence found:
Grant County Survey Records show no
previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the
original location of this corner:
Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 12" in the ground & raised a mound of stone & earth
around the pipe.
From Which:
A Juniper 16" dia., Bears S28°W., 9.4 ft., scribed: C1/4 S28 BT
A Juniper 8" dia., Bears S54°W., 57.0 ft., scribed: C1/4 S28 BT
Measurements to trees taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing
Tree Sign above blaze, and warning sign on back of each tree. Painted
a 6" red band at breast ht. around each tree. Set steel fence posts with
warning & Boundary Signs, South & West 5 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1969
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: May 13, 1985
Refer to Map of Survey No. 913

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 17 day of Mar, 1986
Douglas M. Ferguson by _____
(COUNTY OFFICIAL) (DEPUTY)