

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. T-23

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T10S R30E
C1/4
S25
1985
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 28" in the ground.
From Which.
A Fir 14" dia., Bears S29°W., 9.3 ft., scribed: C1/4 S25 BT
A Fir 16" dia., Bears N69°W., 28.0 ft., scribed: C1/4 S25 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, N25°W., 2.5 ft. from the corner.



This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Aug. 23, 1985
Refer to Map of Survey No. 919

Office of... *Surveyor* ... County of... *Grant* ...
State of... *Oregon* ... I hereby certify that the within instrument was filed in this office
for record on the... *12* day of... *Mar* ... 19... *86* ...
Robert P. Magott by _____
(COUNTY OFFICIAL) (DEPUTY)