

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. V-7

History of original corner establishment:

Corner was originally established in Sept. 1873, By W.M. Byars, U.S. Deputy Surveyor, under Contract No. 197. Surveyor Generals Notes State: Set a Basalt Stone 14x10x6, for the 1/4 Sec. Corner.

DIAGRAM

T10S R30E
S29
1/4-.-
S32
1984
PLS 848

Description of corner evidence found:

Found 14"x12"x6" stone, with 1/4 on west face, set in a mound of stone. N-S fence runs 10 ft. east, fence corner 40 ft. south from stone mound. No accessories originally established. Accepted above described stone as 1/4 corner position.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 3" in the ground, and raised a mound of stone and earth around pipe.

From Which:

A Juniper 10" dia. Bears, N30°E., 17.4 ft., scribed: 1/4 S29 BT

A Pine 14" dia. Bears, S55°W., 135.0 ft., scribed: 1/4 S32 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, in the stone mound, North & East 1 ft. from the pipe.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Nov. 7, 1985
Refer to Map of Survey No. 908

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 12 day of Mar, 1986
Robert D. Bayle by _____
(COUNTY OFFICIAL) (DEPUTY)