# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**History of original corner establishment:**
New Corner

DIAGRAM
T10S R31E
SE1/16
+
S2

**Description of corner evidence found:**

**Description of monument and accessories I establish to perpetuate the original location of this corner:**
Set a 2½x28" aluminum monument 10" in the ground in a mound of stone.
I establish new bearing trees:
A 7" P.Pine bears N 88½° W, 89.6 ft, scribed SE1/16S2BT.
A 9" P.Pine bears S 18½° E, 86.9 ft, scribed SE1/16S2BT.

T10S R31E
SE1/16
+
S2
PLS1918
1988

New BTs have 3/4" brass washers marked PLS1918 attached to the BT blaze, faces and bands painted with red tree marking paint, and BT tags and Attention or Land Survey Monument signs. A steel fence post with Attention or Land Survey Monument sign is driven approximately 3-5 feet from the corner.

Sun Cadastral Survey, Cont No. 53-04H1-7-4011
Field Book:4-28
Work accomplished: 8/17/88
Witnesses: Louise Parsons, Douglas Parsons
Job No.: 87221

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Tyler B Parsons
OREGON
JULY 18, 1980
TYLER B. PARSONS
1918

PARSONS SURVEYING
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515

Office of COUNTY SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office for record on the 7th day of June, 1989

Robert L Daggett
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)