

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Rufus S. Moore, US Deputy Surveyor, during the original survey Contract No. 382 dated March, 1881. Set a basalt stone 15x4x5 and dug pits for 1/4 sec. cor.

DIAGRAM

T10S R31E

1/4

S 8 | S 9

1989

PLS 699

Description of corner evidence found:

There were too many rocks of near dimensions and with no apparent chisel marks could not find the original stone.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 2 1/2" aluminum cap, marked as shown in the diagram, 22" in the ground to hardpan, at single proportionate measurements from adjacent found corners. Built a mound of rock to be 44" in diameter by 8" high around the monument, from which new BTs are:

11" Juniper bears N34°15'W, 177.5 feet scribed 1/4 S8 BT

10" Juniper bears N17°E, 191.6 feet scribed 1/4 S9 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between corners G-13 and N-13 as shown on Grant County Map of Survey No. 634, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set steel fence posts 5 feet S and 5 feet N of the corner on the National Forest boundary lines. Attached Forest Boundary signs to each post and an Attention sign to the S post.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 7/, 1989, I re-established the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR
THIS 26 DAY OF July, 1990

Robert D. Baggett
Grant County Surveyor

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers

OREGON
JULY 9, 1965
LELAND LEE MYERS
699