


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally set by Rufus S. Moore, Deputy U.S. Surveyor, under his contract No. 382 dated March 1881.

Original Notes: Set a basalt stone 12x12x8 and raised mound of stone for 1/4 sec. cor.



Description of corner evidence found:

A stone closely matching the dimensions of the original monument beneath a rock jack on a N-S fence at its intersection with the remains of an ancient fence to the west. This stone confirmed as the original to Frank Palmer by the adjoining land owner.


No bearing trees or other official accessories found.

Description of monument and accessories established to perpetuate the original location of this corner

At the corner location I set a 2½"x30" aluminum monument with a magent in the base and a 3½" cap stamped as shown. I bury the original stone in the mound on the south side of the monument.

A 15" juniper with double ax face brs. N79 E a dist. of 66.3 ft. scribed "1/4 S22 BT". A 16" juniper with double ax face brs. N40½ W a dist. of 219.4 ft. scribed "1/4 S21 BT".

All new trees tagged with brass washer "PLS 1078".



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Clell Goodwin

OREGON
JULY 30, 1976
**CLELL GOODWIN
1078**

I hereby certify the above corner monument was re-established as herein described on September 2, 1980.

Clell Goodwin, P.L.S.
Witness: /s/ L.Kinart

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 31 day of Oct 1980
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)