


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally set in a survey dated 9/30/80 by Clell Goodwin, PLS 1078, for the USFS under Cadastral Contract No. 53-04H1-9-7631N.



Description of corner evidence found:


NONE

Description of monument and accessories established to perpetuate the original location of this corner

At the corner location as determined by a survey of said section I set a 2 1/2"x30" aluminum monument with magnet in the base and a cap stamped as shown.

A 10" juniper with double ax face brs. N63 W a dist. of 26.0 ft. scribed "C1/4 S22 BT". A 14" juniper with double ax face brs. S35 E a dist. of 27.8 ft. scribed "C1/4 S22 BT".

All new trees tagged with brass washer "PLS 1078".



**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Clell Goodwin*

OREGON  
JULY 30, 1976  
**CLELL GOODWIN**  
1078

I hereby certify the above corner monument was re-established as herein described on September 2, 1980.

Clell Goodwin, P.L.S.  
Witness: /s/ L. Kinart

Office of Surveyor County of Grant  
 State of Oregon, I hereby certify that the within instrument was filed in this office  
 for record on the 31 day of Oct 1980  
Robert D. Baggett by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)