


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally set by Rufus S. Moore, Deputy U.S. Surveyor, under his Contract No. 382 dated March 1881.

Original Notes: Set a pine post for 1/4 Sec. Cor. from which:

- A B. Pine 15 in. dia. bears S 51° E 47 lks. dist.
- A Y. Pine 10 in. dia. bears N 12° E 17 lks. dist.



Description of corner evidence found:

No corner monument found.

Fd. OBT was 15" pine now 18" snag dead and down with visible scribe. "BT" brs. S51° E a dist. of 31.0 ft. (S51E 47 lks.)


No sign of NE BT which was destroyed by road construction.

Description of monument and accessories I established to perpetuate the original location of this corner

At the record bearing and distance from the original SE BT, I set a 2½" x 30" aluminum monument with magnet in the base and a 3½" cap stamped as shown.

A 25" pine with double ax face brs. N84°E a dist. of 22.7 ft. Scribed "1/4 S22 BT". A 12" spruce with double ax face brs. S10°W a dist. of 59.5 ft. Scribed "1/4 S27 BT".

All new trees tagged with brass washer "PLS 1632".



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Richard Clark

**OREGON
JULY 14, 1978
RICHARD CLARK
1632**

I hereby certify the above corner monument was re-established as herein described on July 16, 1980.

Richard Clark, P.L.S.
Witnesses: /s/ C. Goodwin
L. Kinart

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 31 day of Oct 1980
Robert D. Dwyer by _____
(COUNTY OFFICIAL) (DEPUTY)

R-15