


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**

Corner originally set in a survey dated 9/15/80 by Clell Goodwin, PLS 1078, for the USFS under Cadastral Contract No. 53-04H1-9-7631N.



**Description of corner evidence found:**


NONE

**Description of monument and accessories I established to perpetuate the original location of this corner**

At the corner location as determined by a survey of said sections I set a 2½"x30" aluminum monument with magnet in base and a 3½" cap stamped as shown.

A 9" fir with double ax face brs. S22½ E a dist. of 8.2 ft. scribed "W1/16 S34 BT". A 10" fir with double ax face brs. N6 W a dist. of 51.3 ft. scribed "W1/16 S27 BT".

All new trees tagged with brass washer "PLS 1078".



**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Clell Goodwin*

OREGON  
JULY 30, 1976  
**CLELL GOODWIN**  
1078

I hereby certify the above corner monument was re-established as herein described on August 29, 1980.

Clell Goodwin, P.L.S.  
Witness: /s/ L. Kinart

Office of Surveyor County of Grant  
 State of Oregon, I hereby certify that the within instrument was filed in this office  
 for record on the 31 day of Oct 1980  
Robert D. Bagers by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)

V-14