


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally set by Rufus S. Moore, Deputy U.S. Surveyor, under his contract No. 382 dated March 1881.

Original Notes: Set basalt stone 18x8x8 and raised a mound of stone for 1/4 Sec. Cor.

Corner reset by proportional measurement in a survey dated 8/30/80 by Clell Goodwin, PLS 1078, for the USFS under Cadastral Contract No. 53-04H1-9-7631N.



Description of corner evidence found:


NONE

Description of monument and accessories I established to perpetuate the original location of this corner

There has been a considerable amount of ground disturbance in the area of the corner and I find no indication of the original monument. At the corner location as determined by a survey of the section line, I set a 2 1/2"x30" aluminum monument with a magnet in base and a 3 1/2" cap stamped as shown.

A 25" pine with double ax face brs. S19 1/2 E a dist. of 168.0 ft. scribed "1/4 S36 BT". A 6" pine with double ax face brs. N36 E a dist. of 28.7 ft. scribed "1/4 S25 BT".

All new trees tagged with brass washer "PLS 1632".



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Richard Clark

OREGON
JULY 14, 1978
RICHARD CLARK
1632

I hereby certify the above corner monument was re-established as herein described on August 5, 1980.

Richard C. Clark, P.L.S.
Witness: /s/ L. Kinart

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 31 day of Oct 1980
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)

V-23