

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: *

The original corner was established in 1881 by Rufus S. Moore under Contract No. 382.
The original notes state:
North between sections 29 and 32
40.00 Set Alder post for 1/4 sec corner in mound of earth with pits as per instructions.
40.10 To brook 2 lks wide runs NE.

DIAGRAM
T10S R31E
1/4
S311S32

Description of corner evidence found:

Found no evidence of the original corner.

Description of monument and accessories I establish to perpetuate the original location of this corner:


I reestablish this corner by single proportion. Corner position falls in a small stream. Set witness corner S 0°04'42" E, 15.59 ft from true corner position. Set a 2-1/2"x30" aluminum monument 20" in the ground in a mound of stone for WC.
I establish new bearing trees:
A 5" double Yew bears S 42° W, 29.4 ft, scribed XBT.
A 13" Fir bears N 50°07' E, 11.2 ft, scribed XBT.

T10S R31E
WC 1/4
^
S311S32
PLS1918
1989

Sun Cadastral Survey
Contract No.: 53-04H1-7-4011
Project No.: 8722JB
Field Book: 7-37
Work Accomplished: 4/10/89
Witnesses: Louise Parsons

New BTs have 3/4" brass washers marked PLS1918 attached to the BT blaze, faces and bands painted with red tree marking paint, and BT tags and Attention or Land Survey Monument signs. A steel fence post with Attention or Land Survey Monument sign is driven approximately 3-5 feet from the corner.

PARSONS SURVEYING
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515



Office of COUNTY SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office for record on the 26 day of June, 1987

Robert D. Bayart by _____
(COUNTY OFFICIAL) (DEPUTY)