


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally set in a survey dated 9/15/80 by Clell Goodwin, PLS 1078, for the USFS under Cadastral contract No. 53-04H1-9-7631N.




Description of corner evidence found:

NONE

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner location as determined by a survey of said section I set a 2 1/2"x30" aluminum monument with a magnet in base and a 3 1/2" cap stamped as shown.



A 15" fir with double ax face brs. S41 W a dist. of 36.7 ft. scribed "C1/4 S34 BT". A 10" fir with double ax face brs. N18 W a dist. of 44.9 ft. scribed "C1/4 S34 BT".

All new trees tagged with brass washer: "PLS 1078".



*Clell Goodwin*



I hereby certify the above corner monument was re-established as herein described on August 29, 1980.

Clell Goodwin, P.L.S.  
Witness: /s/ L. Kinart

Office of Surveyor County of Grant  
 State of Oregon, I hereby certify that the within instrument was filed in this office  
 for record on the 31 day of Oct 1980  
Robert D. Baggett by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)

X-15