

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1969, Duanne I. Griffith, PLS 644, set a 5/8" x 30" iron pin as the southwest corner of a parcel of land located in T.10S., R.32E., Section 11. See Grant County Map of Survey No. 157.

DIAGRAM  
T10S R32E  
Sec 11  
SW  
LOT  
COR  
1992  
PLS 2405

Description of Corner Evidence Found:

Found a 5/8" rebar, with no cap, as set by Duanne I. Griffith, PLS 644.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown on the DIAGRAM, 25" in the ground. Placed the found rebar inside my monument.

As references set a 5/8" x 30" rebars with yellow plastic cap marked PLS 2405, 28" in the ground, which bear as follows:

S02°15'W, 19.5 ft.  
S81°30'E, 25.9 ft.

Measurements to rebars taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' easterly and northerly of the monument on boundary lines.

This work was performed by:  
Susan E. Newstetter, PLS 2405  
Witnessed by: D. Mitchell Ferguson  
and Rick Saul  
October 7, 1992  
Refer to Grant Co. Survey No.: 1237

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Susan E. Newstetter*

OREGON  
JULY 26, 1989  
SUSAN E. NEWSTETTER  
2405

Exp. Date 12/31/92

Office of Surveyor County of Grant  
State of OR I hereby certify that the within instrument was  
filed in this office for record on the 30 day of Nov, 1992  
Robert D. Bayett by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)