

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original corner was established by Robb & Gradon in 1881 under Contract No. 383, dated March 26, 1881.

DIAGRAM
T10S R32E

The original notes state:

North between Secs 11 & 12
40.00 Set stone 15x10x4 in stone mound for 1/4 sec cor.

1/4
S111S12

Description of corner evidence found:

Found no evidence of the original corner. The expected corner position falls in an area severely disturbed by placer mining.

Description of monument and accessories I establish to perpetuate the original location of this corner:


I reestablished this corner by single proportion. Set a 2x30" aluminum monument 20" in the ground in a mound of stone.
A 1 1/2" aluminum cap on 5/8" rebar bears S86°57'W 12.32 ft, marked RM 1/4S11 PLS1918.
A 1 1/2" aluminum cap on 5/8" rebar bears S22°50'E 9.83 ft, marked RM 1/4S12 PLS1918.

T10S R32E
1/4
S111S12
PLS1918
1989

New BTs have 3/4" brass washers marked PLS1918 attached to the BT blaze, faces and bands painted with red tree marking paint, and BT tags and Land Survey Monument signs. A steel fence post with Land Survey Monument sign is driven approximately 3-5 feet from the corner.

Sun Cadastral Survey, 53-04H1-7-4011
Project No. 8722LC
Field Book: 8-17
Work Accomplished: 9/2/89
Witnesses: Louise Parsons

PARSONS SURVEYING
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515



Office of County Surveyor County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 21 day of Nov, 19 89

Robert D. Dugan by _____
(COUNTY OFFICIAL) (DEPUTY)