

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
New corner

DIAGRAM
T10S R32E
CSSW1/64
GALENA!
-----+--
|
S12
PLS1918
1989

Description of corner evidence found:

Description of monument and accessories I establish to perpetuate the original location of this corner:


Set a 2 1/2 x 30" aluminum monument 22" in the ground in a mound of stone. A 1" pipe shown in CS 365 as on the easterly right of way of Galena, bears S47°41'W 2.53 ft.
An 11" P.Pine bears N80°47'E 52.7 ft, scribed CSSW1/64S12BT.
A 12" P.Pine bears S28°18'E 100.4 ft, scribed CSSW1/64S12BT.

T10S R32E
CSSW1/64
GALENA!
-----+--
|
S12
PLS1918
1989

New BTs have 3/4" brass washers marked PLS1918 attached to the BT blaze, faces and bands painted with red tree marking paint, and BT tags and Land Survey Monument signs. A steel fence post with Land Survey Monument sign is driven approximately 3-5 feet from the corner.

Sun Cadastral Survey, 53-04H1-7-4011
Project No. 8722LC
Field Book: 8-20
Work Accomplished: 9/6/89
Witnesses: Louise Parsons

PARSONS SURVEYING
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515



Office of County Surveyor County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 21 day of Nov, 19 89

Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)