

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
The corner was established by H. Gradon in 1881 under
Contract No. 383. The original notes state:

DIAGRAM
T10S R32E
1/4
S14/S13

North between Sec 13 & 14
40.00 Set stone 18x10x6 for 1/4 Sec cor from which
A pine 36 in dia bears S73°W 43 1ks dist
A pine 36 in dia bears S80°E 167 1ks dist

Description of corner evidence found:
Found no evidence of the original corner.


Description of monument and accessories I establish to perpetuate the
original location of this corner:
Set a 2-1/2" aluminum monument 22" in the ground.
New BTs:
A 10" Pine bears S 24°11'E 21.6 ft scribed 1/4S13BT.
A 13" Pine bears S72°28'W 62.4 ft scribed 1/4S14BT.

T10S R32E
1/4
S14/S13
PLS1918
1989

New BTs have 3/4" brass washers marked PLS1918 attached to the BT
blaze, faces and bands painted with red tree marking paint, and
BT tags and Attention or Land Survey Monument signs. A steel fence
post with Attention or Land Survey Monument sign is driven
approximately 3-5 feet from the corner.

Sun Cadastral Survey
Contract No.: 53-04H1-7-4011
Project No.: 8722LB
Field Book: 7-69
Work Accomplished: 6/6/89
Witnesses: Louise Parsons

PARSONS SURVEYING
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515



Office of COUNTY SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 10 day of Aug, 1989
Robert D. Bayart by _____
(COUNTY OFFICIAL) (DEPUTY)