

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


SEE GRANT

RECORD SURVEY

INDEX NO. ^{NO} C-6 1098

History of original corner establishment:

None. Corner was established as part of this survey.



Description of corner evidence found:

None - there is an old location poster on a 18" fir brs S4°W, 27' from corner point.

Description of monument and accessories | established to perpetuate the original location of this corner:

At position determined by survey...Set a 2½" x 30" aluminum pipe with 2½" aluminum cap 24" in ground & surrounded with mound of earth & stone. Cap marked as shown in corner diagram.

New bearing trees established:

A 17" ponderosa pine brs S14°E, 9.4' scribed C-W1/16S5 BT.

A 6" ponderosa pine brs S51½°E, 41.5' scribed C-W1/16S5 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-4 to each BT & painted face of blaze & 6" red band around each BT. Set steel fence post E of corner & attached sign 54-9.

Compass declination 18° East.

I hereby certify that the above corner was properly established by me to U.S.F.S. standards and witnessed by Bill Quaempts on July 13, 1989.



Office of.....County Surveyor.....County of.....Grant.....
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the 22 day of Mar, 1990
Robert J. [Signature] by
 (COUNTY OFFICIAL) (DEPUTY)

C-6